



Схема расположения колонн на отм. 0,000



A-A (1:100)(1/4)



Ведомость элементов

Марка элемента	Сечение			Усилие для прикрепления			Наименование или марка металла	Примечание
	эскиз	поз.	состав	A, кН	N, кН	M, кН.м		
K1		1	II 35K2				C245	
		2	-40				C245	
		3	-20				C245	
		4	-8				C245	
K2		1	II 35K2				C245	
		2	-40				C245	
		3	-20				C245	
		4	-8				C245	
K3		1	II 35K2				C245	
		2	-40				C245	
		3	-20				C245	
		4	-10				C245	
		5	-8				C245	
K4		1	II 25K2				C245	
		2	-20				C245	
		3	-10				C245	
		4	L100x100x6,5				C245	
П1,П2			Г 22П				C245	
CB1		1	L 70x70x6				C245	
		2	-8				C245	
CB2			Г 22П				C245	
P1		1	L 70x70x6				C245	
		2	-8				C245	
Ф1	Сложное сечение							
СГ1-СГ3		1	L 70x70x6				C245	
		2	-8				C245	
СГ4-СГ5		1	L 70x70x6				C245	
		2	-8				C245	
ШЛ1	—		-8				C245	
a	—		-8				C245	
b	—		-30				C245	
b	—		-18				C245	
z	L		L 70x70x8				C245	
g	Г		Г 22П				C245	
e	□		□100x100x6				C245	
ж	—		-20				C245	

* Размер для справок